


TPO 177 Land at Boyne House 55 Blackwater Road, Eastbourne supporting photographs.

A. Shows an area of concrete retaining wall which has moved, possibly causing direct damage to the adjacent brick wall indicated as **B.** The brick wall (B) is the wall at the centre of the objection.







Points of failure
to brick wall (B)

